

VEHICLE INSPECTION REPORT

SJ71HSO

Fiat Doblo Work Up 1.6 MULTIJET 16V II

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 02/11/2021

Year 2021

Mileage 74,617 Miles
Warranted

Fuel Type Diesel

Colour WHITE

VIN ZFA26300006V19811

Body Style Dropside L2

MOT Due 16/09/2026

CAP Clean £6,500.00

CAP Average £5,925.00

CAP Below £4,975.00

Gearbox MANUAL

Gears 5

BRAKE LIGHT INOP AD-BLUE

Tyres

NSF

NSR

OSF

OSR

Spare

Features


- Park assist camera
- Front electric windows
- Cloth seat trim
- Rear parking sensor
- Drivers airbag
- Digital radio
- Passenger airbag
- Radio/CD
- Central locking

Photos





Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front
Scratched
Over 100mm Thru Paint



3: Wing nsf
Dented
With Paint Damage



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Door Mirror Assy nsf
Scuffed (Unpainted)
Over 100mm



6: Door nsf
Dented
Over 30mm



7: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



8: B Post os
Dented
Over 30mm




9: Wing osf
Scratched
Over 25mm Thru Paint



10: Fascia Panel
Missing
Replace



11: Carpets Front
Holed
Over 3mm



12: Seat Base Cover osf
Torn
Over 3mm



13: Seat Back Cover osf
Holed
Over 3mm



14: Fascia Panel
Missing
Replace

Interior

Carpet Condition	Poor	Upholstery Condition	Poor
Seat Condition	Poor	Odour	No
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		