COMMERCIAL VEHICLE AUCTIONS LTD
THE UK'S MOST ESTABLISHED COMMERCIAL VEHICLE AUCTIONEERS

Carr Hill Industrial Estate
Doncaster
DN4 8DE
01302 732600 | cva.noreply@cva-auctions.co.uk

VEHICLE INSPECTION REPORT

LO69LPN

Ford Ranger 2.0 ECOBLUE 170PS

Inspection

Serious Damage?	No

Vehicle

VAT	Plus VAT
V5	Present
Cap Id	44058
Cap Code	FORA20XLT 7DTM4 6 L

Details

Location	Bedford	**Colour**	WHITE	**CAP Below**	£4,800.00
Reg. date	31/12/2019	**VIN**	6FPPXXMJ2PKS28900	**Gearbox**	MANUAL
Year	2019	**Body Style**	Pickup Double Cab	**Gears**	6
Mileage	105,222 Miles Warranted	**MOT Due**	10/11/2026	**Axle Combi**	4x4
Fuel Type	DIESEL	**CAP Clean**	£7,150.00		
GVW	3270kg	**CAP Average**	£6,150.00		

WARNING LIGHTS ON DASH *PARTIALLY STRIPPED, AIRBAGS GONE OFF, WINDSCREEN CRACKED* TOW BAR

Tyres

NSF	
NSR	
OSF	
OSR	
Spare	

Features

- Air conditioning
- Front electric windows

Photos









Trip computer 1
Speed
0
mph



L069 LPN

FORD
e5*2007/46*0080
6FPPXXMJ2PKS28900
3270 KG
6000 KG
1480 KG
1850 KG
2AB
0.50


L069 LPN





GENERAL

TIA
BFGoodrich


TIA
All-Terrain


GENERAL





Condition Check



Damage Photos



1: Wing osf
Dented
With Paint Damage



2: Wing osf
Scratched
UpTo 25mm Thru Paint



3: Bumper Front
Cracked
Over 25mm



4: Screen Front
Cracked
Replace



5: Bonnet
Dented
With Paint Damage



6: Wing nsf
Dented
With Paint Damage



7: Door Mirror Assy nsf
Scuffed (Unpainted)
UpTo 100mm



8: Centre Console Front
Broken
Replace



9: C Post ns
Dented
With Paint Damage



10: Qtr Panel nsr
Scratched
Over 25mm Thru Paint



11: Qtr Panel nsr
Dented
Between 10mm + 30mm



12: Bumper Rear
Rusted
Over 5mm



13: Door osf
Chipped
Edge Chip



14: Centre Console Front
Broken
Replace



15: Sill os
Rusted
Over 5mm



16: Steering Wheel
Damaged
Replace



17: In Car Entertainment
Missing
Replace

Interior

Carpet Condition	Average	**Upholstery Condition**	Average
Seat Condition	Average	**Odour**	No

Engine Runs	OK	Gearbox 1st and Reverse Test	OK
Brakes	OK	Clutch Slip Test from Static	OK
Parking Brake	OK	Gearbox Static Gear Selection (engine running)	OK
		No Excessive Smoking	OK
EML light illuminated	OK	Oil warning light illuminated	OK
Airbag light illuminated	Fault	DPF light illuminated	Fault
ABS light illuminated	OK	Service indicator light illuminated	OK